

PHOTOGRAPH 1, ROLL 1 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: W
Description: Silver recovery unit in X-ray Film Developing Area




PHOTOGRAPH 2, ROLL 1 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: W
Description: Hazardous waste satellite accumulation area (HWSAA) drum for waste methanol, ethanol, and methyl isobutyl ketone (TRUPACT maintenance area)



PHOTOGRAPH 3, ROLL 1 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: W
Description: HWSAA for waste alcohol in Pipe OVERPAK
Project Area (TRUPACT maintenance area)



PHOTOGRAPH 4, ROLL 1 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: NW
Description: Two fiberboard boxes of rags soaked with
Magnaflux cleaner in Pipe OVERPAK Project Area



PHOTOGRAPH 5, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: Fifty-five-gallon drum containing waste oil-water
 coolant mix; drum was stored at S end of Fabrication Building.



PHOTOGRAPH 6, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NE
 Description: Open 55-gallon drum with unknown contents
 (no label); drum was stored at S end of Fabrication Building



PHOTOGRAPH 7, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: N
 Description: South Less-than-90-day Storage Area; note
 missing bungs and lack of labels



PHOTOGRAPH 8, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: E
 Description: South Less-than-90-day Storage Area; note
 missing bungs and lack of labels



PHOTOGRAPH 9, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: N/NE
 Description: South Less-than-90-day Storage Area; note missing bungs and lack of labels



PHOTOGRAPH 10, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: One of three unlabeled drums with unknown contents in the South Less-than-90-day Storage Area



PHOTOGRAPH 11, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: E
 Description: One of four open 55-gallon drums in South
 Less-than-90-day Storage Area labeled "Denatured Alcohol."



PHOTOGRAPH 12, ROLL 1 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: E
 Description: View inside scrap metal container where
 aerosol cans (not punctured) and other miscellaneous
 trash are disposed of



PHOTOGRAPH 13, ROLL 1 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: E
Description: Open scrap metal container containing aerosol cans (not punctured) and other miscellaneous trash; note lack of hazardous waste label



PHOTOGRAPH 1, ROLL 2 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: E
Description: Scrap metal storage area; one roll-off box contained stainless-steel shavings (on left) and the other contained stainless-steel solids (on right)




PHOTOGRAPH 2, ROLL 2 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: N
Description: North Less-than-90-day Storage Area




PHOTOGRAPH 3, ROLL 2 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: NW
Description: North Less-than-90-day Storage Area




PHOTOGRAPH 4, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: SW
 Description: Black 55-gallon poly drum containing corrosive
 "Lab Only" and "titration waste" located in North
 Less-than-90-day Storage Area; drum has accumulation
 start date of 1/1/97.



PHOTOGRAPH 5, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: Open leaking 55-gallon drum with no label
 or accumulation start date; drum located in North
 Less-than-90-day Storage Area



PHOTOGRAPH 6, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: N
 Description: Open 55-gallon drum with unknown contents
 and no accumulation date



PHOTOGRAPH 7, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: Open 55-gallon poly drum with unknown
 contents



PHOTOGRAPH 8, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NE
 Description: Open 5-gallon bucket with unknown contents;
 note other 5-gallon buckets with lids



PHOTOGRAPH 9, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation:
 Description: Two open 5-gallon buckets with no label
 or accumulation start date; drum located in North
 Less-than-90-day Storage Area



PHOTOGRAPH 10, ROLL 2 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: E
 Description: North Less-than-90-day Storage Area; note
 about 12 drums with various contents staged outside
 of fenced area.



PHOTOGRAPH 1, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: North Less-than-90-day Storage Area; three
 55-gallon drums filled with discarded aerosol cans
 (unpunctured)



PHOTOGRAPH 2, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: N
 Description: North Less-than-90-day Storage Area; 55-gallon drum labeled "Dirty Alcohol;" no hazardous waste label or accumulation start date



PHOTOGRAPH 3, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: W
 Description: North Less-than-90-day Storage Area; 5-gallon poly buckets stored in secondary containment; facility personnel stated that they contained used gear oil.



PHOTOGRAPH 4, ROLL3 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: NW
Description: North Less-than-90-day Storage Area; open
55-gallon drum labeled "Denatured Alcohol" with missing
bung (sample identification WEPD1-DRUM3-03 & -04)



PHOTOGRAPH 5, ROLL3 01/16/02
WESTINGHOUSE SIERRA VISTA FACILITY
Orientation: NW
Description: North Less-than-90-day Storage Area; open
55-gallon drum labeled "Denatured Alcohol" with missing
bung (sample identification WEPD1-DRUM3-03 & -04)




PHOTOGRAPH 6, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation:
 Description: North Less-than-90-day Storage Area




PHOTOGRAPH 7, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: 500-gallon used oil tank located within
 secondary containment in North Less-than-90-day Storage
 Area



PHOTOGRAPH 8, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: SE
 Description: North Less-than-90-day Storage Area; standing liquid, booms, shavings, floor dust, oil, and sludge that has accumulated within secondary containment basin



PHOTOGRAPH 9, ROLL3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: E
 Description: North Less-than-90-day Storage Area;
 55-gallon poly drum labeled "Sodium Hydroxide (UN1824)"



PHOTOGRAPH 10, ROLL 3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: E
 Description: North Less-than-90-day Storage Area;
 55-gallon poly drum with no label and unknown contents
 in secondary containment



PHOTOGRAPH 11, ROLL 3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: NW
 Description: North Less-than-90-day Storage Area;
 55-gallon drums of used oil in secondary containment



PHOTOGRAPH 12, ROLL 3 01/16/02
 WESTINGHOUSE SIERRA VISTA FACILITY
 Orientation: SE
 Description: North Less-than-90-day Storage Area; blue
 poly drum labeled "Dirty Rags;" open drum containing
 empty aerosol cans to the right



PHOTOGRAPH 1, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: W
 Description: HWSAA drums for waste paint and waste
 thinner




PHOTOGRAPH 2, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: NW
 Description: Sandblasting Area on NW side of Fabrication
 Building (sample identification WEPD2-BLAST1-05)




PHOTOGRAPH 3, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: N
 Description: Pile of spent blast sand located NW of the
 Sandblasting Area
 (sample identification WEPD2-BLAST2-06 and -07)



PHOTOGRAPH 4, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: W
 Description: Overview of the Less-than-90-day Storage Area
 NW of Fabrication Building




PHOTOGRAPH 5, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: SW
 Description: Open poly container with unknown liquid in
 Less-than-90-day Storage Area



PHOTOGRAPH 6, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: W
 Description: Open 55-gallon drum with unknown liquid
 staged within secondary containment in Less-than-90-day
 Storage Area; appears to be oil-coolant mix



PHOTOGRAPH 7, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: W
 Description: Less-than-90-day Storage Area; 55-gallon
 drums labeled "Waste Paint" (left) and "Waste Thinner"
 (right) staged within secondary containment; no dates
 or label



PHOTOGRAPH 8, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: W
 Description: Open 55-gallon drum with unknown liquid;
 bungs were removed; no date or label (Drum 3 was not
 sampled based on hazard characterization [HAZCAT])



PHOTOGRAPH 9, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: NE
 Description: Overview of outdoor drum storage area on
 other side of fence from Less-than-90-day Storage Area;
 open drums contain drying paint.



PHOTOGRAPH 10, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: NE
 Description: Drying paint within 55-gallon drum in outdoor drum storage area



PHOTOGRAPH 11, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: NE
 Description: Overpack drum used for drying paint in outdoor drum storage area



PHOTOGRAPH 12, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: NE
 Description: Fifty-five-gallon drum within overpack with
 unknown contents (WEPD2-DRUM4-04)



PHOTOGRAPH 13, ROLL 4 01/16/02
 WESTINGHOUSE EAST GREENE FACILITY
 Orientation: E
 Description: On left, 55-gallon drum within white poly
 overpack container (WEPD2-DRUM4-04); on right, red
 55-gallon "Citgo" drum (Drum 5 was not sampled based
 on HAZCAT)